

TICKET #IE314_147

There was an intermittent mechanical vibration (pulsing) in both the LH and RH joy sticks during the subjective flyout.

23-03-2023

I opened ticket with Alsim, discussed it with Alsim's Engineer. We agreed that in the past this has been caused by a faulty potentiometer.

This has been replaced and a placard erected in the SIM asking to report ANY "vibrating" as top priority.

We will leave this placard in place.

[Placard](#) (Click to open)

VIBRATION ON "YOKES".

INSTRUCTORS:

Please note - During the 2023 evaluation, there was a mechanical vibration felt in the "YOKES".

We hope that this is resolved. "IF" you or the student feels any incorrect vibrations on the YOKE - Please report to the FSTD Manager and create a ticket using the ticketing system

FSTD MANAGER MICHAEL SMITH 085-2621642



Still On display - but there were no reports of this recurring - Feb 2024.
Michael