

**TICKET #IE314\_142**

**DECLARED - Item 6.1.C.9 from 2019 report remains open: No air available from air vents installed on the LHS and RHS of the cockpit instrument panel.**

**27-03-2023**

Arranged with KLM electrical (Steven) to install an air vent behind the 314 and a switch in the SIM to activate/deactivate due end of March 2023

**16-04-2023**

Spoke to KLM looking for an update. Parts have arrived and are in stock. Promised to get an electrician on site the week starting the 24th April for installation.

**01-07-2023**

Fan installed behind simulator. Connected to both pilot and copilot air vents and an off/on switch installed within the simulator. Closing this ticket.

